



Ariens Company
655 W. Ryan St.
Brillion, WI 54110
www.ariens.com

Service Bulletin

Product Family: National 995305 Triplex Mower and Locke 995310, 313 and 318 Reel Mowers

Subject: Engine Operating Speed

Dealer Action: Check and Adjust Operating Speed

Model	Serial Number Range	Description	Required Operating Speed (RPM)
995305	000119 – 000131	National 8400 Triplex Mower	3100
995310	000101 – 000119	Locke CL-125 Commercial Reel Mower	2300
995313	000101	Locke CL-130 Commercial Reel Mower	3000
995318	000101 – 000108	Locke CL-136 Commercial Reel Mower	3000

Ariens Company has learned that models in the above serial number ranges may have left the factory with their operating speed set incorrectly.

Distributors with these models in inventory are to check and reset the operating speed as necessary to the required setting before releasing.

Dealers with these models in inventory are to check and reset the operating speed as necessary to the required setting before selling the unit to a customer.

Customers who have purchased any of these models are to be notified that the operating speed needs to be checked and adjusted as necessary the next time that the unit is brought in for service.

Checking and adjusting the operating speed on the above units will be covered under the unit's standard warranty terms. Dealers or distributors will be reimbursed .5 hour at their standard posted shop labor rate for performing the procedure.