



Ariens Company 655 W. Ryan St. Brillion, WI 54110 www.gravely.com

Product Family: Yamaha-Powered Gravely Zero-Turn Mowers Subject: Troubleshooting and Repair Information Available

Dealer Action: Read and Understand Procedures

Model	Serial Number	Description
992281	60,000 and up	Pro-Turn 260 Yamaha MX775V
992282		Pro-Turn 452 Yamaha MX775V
992283		Pro-Turn 460 Yamaha MX825V
992284		Pro-Turn 472 Yamaha MX825V
992288		Pro-Turn 460 Yamaha MX825V CARB
992289		Pro-Turn 452 Yamaha MX775V CARB
992290		Pro-Turn 472 Yamaha MX825V CARB
992291		Pro-Turn 252 Yamaha MX775V CARB
992292		Pro-Turn 260 Yamaha MX775V CARB
992293		Pro-Turn 272 Yamaha MX825V CARB
992294		Pro-Turn 252 Yamaha MX775V
992295		Pro-Turn 272 Yamaha MX825V

Gravely recently introduced the Yamaha MX775V-EFI and MX825V-EFI engines on the Gravely Pro-Turn 200 and 400 models.

Since this is a new engine and fuel system, dealers and technicians may be unfamiliar with the troubleshooting steps required to diagnose and repair these engines.

To ensure proper service, Gravely has made a comprehensive engine service manual available for troubleshooting and repair procedures. This service manual can be found at, and downloaded from, the Dealer Extranet website under Manuals & Documents, and then All Product Manuals.

Navigate to the manual by entering the model number and any serial number above 60000 and select Service Manual.

For more training please visit the Dealer Support Portal Training tab to view additional Yamaha EFI training material or by searching Yamaha EFI Training.

For additional information, dealers may visit the Dealer Extranet page on the Internet. Click on the "Dealer Support Portal" button, then click the "Ask a Question" tab to submit a comment or question to the Dealer Support team.