



# Service Bulletin

Ariens Company  
655 W. Ryan St.  
Brillion, WI 54110-1072  
www.ariens.com

**Product Family: Ariens and Gravely BBZ Models 915130 and 915131**

**Subject: Possible Idler Arm Concern**

**Dealer Action: SALES HOLD – Repair Before Putting into Service**

<b>Model</b>	<b>Description</b>	<b>Serial Number Range</b>
915130	Gravely ZT 1334	000101 – 000381
915131	Ariens Zoom 1334	000101 – 002247

## SAFETY NOTICE: SALES HOLD

Ariens Company has been made aware of a possible concern in an idler arm on Models 915130 and 915131.

Please do not retail any of these units in your inventory until the correction kit is in your possession and has been installed on the product. If you have sold any product, we will need the name, address and telephone number of the customer(s) as soon as possible.

If you have any questions in the interim, please contact Ariens Company Technical Service.

We intend to rectify this in a short time.

Thank you,

Ariens Technical Service